

JCS

Thank you for purchasing a JCS remanufactured engine. Your engine has been pre-run and inspected to assure you of trouble free operation. Your valves have been set and the flywheel endplay has been adjusted. **Do not rotate the flywheel until after the distributor is in place or this may cause the drive gear to dislodge itself.**

A temperature indicator tab was installed on the engine block. If it was missing call your dealer or JCS at 626-338-6003. Be careful in moving or lifting your Volkswagen engine. Do not lift by the pushrod tubes as they can be damaged and leak oil. Check all characteristics of the longblock for accurate application and that all mounting holes and studs that apply are proper prior to attaching anything to do with the final installation.

Because the original design of the VW air-cooled engine left it susceptible to over heating it is important that that it be installed and maintained properly. Because the following engine failures are normally caused by improper installation or incorrect adjustment of accessories, which is out of our control, they are rarely covered by warranty. 1.Burnt or seized pistons 2.Loose cylinder heads 3.excessively worn piston rings 4.Engine failure due to low or dirty oil 5.Burnt or bent valves Here are some recommendations during installation. Set ignition timing properly for the year and type engine. Make sure the intake system is free of leaks and adjusted properly. Be sure that the intake manifold is cleaned thoroughly. Adjust the float level and choke properly. The fan belt should be replaced and adjusted properly if at all cracked or worn. Make sure the fan is cleared of debris that would cause a loss of air flow over the engine.

Thanks Again



JCS
15626 CYPRESS STREET
IRWINDALE, CA. 91706

JCS

15626 CYPRESS STREET, IRWINDALE, CA., 91706 (626) 338-6003

JCS QUALITY AIR COOLED ENGINE LIMITED WARRANTY

JCS REBUILT ENGINES are warranted to the original owner to be free from defects in materials and workmanship for a period of one year from date of purchase or 12,000 miles, whichever occurs first, provided the warranty information is returned within one week of installation. A valve adjustment and oil change are required first at 300 miles then at 1,000 miles and then at 3,000 mile intervals.


A failure due to improper installation, overheating incorrect timing, incorrect valve adjustment, contaminated oil, or abuse will not be covered. Warranty shall not apply to engines installed with after market or missing accessories on the engine that in the determination of JCS affected its performance or reliability. Because overheating is caused by improper installation or incorrect adjustment of accessories, JCS ENGINES are not warranted against damage resulting from overheating. This damage shows up as burnt pistons, seized rings or loose cylinder heads.

If a JCS ENGINE is found to be defective in material or workmanship during its applicable limited warranty period and the customer returns (or ships prepaid) the defective longblock, JCS at its option will repair or replace said longblock with no charge to the customer with the exception of delivery charges. JCS will not assume any responsibility for towing, inconvenience or time lost while vehicle is out of service. Our liability under the terms of the warranty is limited to repair or replacement of the long block as supplied. Final determination and authorization with regards to warranty repairs of any degree rests with JCS.

(SEE REVERSE SIDE)

detach & return

Vehicle license # _____ Vehicle mileage _____
Date _____
Model _____ Year _____ Engine serial # _____ Eng Type _____
Customers name on invoice _____ Phone _____
Address _____ City _____ State _____ Zip _____
Name of installing company _____ Phone _____
Address _____ State _____ Zip _____
City _____



I have read the above warranty and am satisfied with the installation
Owners signature _____